
LOWER BEECHMONT MURAL PROJECT



SITE 1: CORNER OF FREEMANS ROAD & NORTH ROAD, LOWER BEECHMONT, 4211.

SITE 2: 88 NORTH ROAD, LOWER BEECHMONT, 4211.

SITE 3: 37 NORTH ROAD, LOWER BEECHMONT, 4211.

SITE 4: CORNER OF NORTH ROAD & BEECHMONT ROAD, LOWER BEECHMONT, 4211.

















SITE 1: CORNER OF FREEMANS ROAD & NORTH ROAD, LOWER BEECHMONT, 4211.











DESCRIPTION

- Steel frame
- Aluminium bench seat
- · Steel perforated mesh screens on sides

EAST FACADE

- Steel perforated mesh on the back
- Concrete Slab on the ground
- · Corrugated roof

NOTES

- Meeting place at the top of Beechmont Road and the start of Freemans Rd (left) and North Rd (right)
- Clear and maintain gutter and drain
- Clean shelter and slab with high pressure
- Frame and screen are in good condition
- Roof and fascia in good condition
- Sloped bush at the back on the bus stop (not seen from the road)















NORTH FACADE SOUTH FACADE EAST FACADE







DESCRIPTION

- Steel frame
- Aluminum bench seat
- Steel perforated mesh screens on sides and rear
- Corrugated roof
- Steel fascia
- Concrete Slab on the ground

- Sloped bushland behind bus stop (rear facade not visible from the road).
- Clear and maintain gutter and drain
- Clean shelter and slab with high pressure
- Frame and screen are in good condition
- View of the shelter from North is partially blocked by a large gum tree















NORTH FACADE

WEST FACADE

SOUTH FACADE







DESCRIPTION

- Steel frame
- Steel sheet sides with rounded edges.
- · Corrugated rear
- Corrugated roof and gutter
- Timber slat bench
- · Concrete Slab on the ground

NOTES

- · Steel sheets have layers of paint that is textured
- Clear and maintain gutter and drain
- Clean shelter and slab with high pressure
- Frame and screen are in good condition
- View of the shelter from North is partially blocked by a large gum tree















SITE 4: CORNER OF NORTH ROAD & BEECHMONT ROAD, LOWER BEECHMONT, 4211.

















SITE 4: CORNER OF NORTH ROAD & BEECHMONT ROAD, LOWER BEECHMONT, 4211.





DESCRIPTION

- Double bus stops on large slag
- Steel frame
- Aluminum bench seat
- Steel perforated mesh screens on sides and rear
- Corrugated roof
- Steel fascia
- Concrete Slab on the ground

NOTES

- Walkway at the rear
- Busy road
- Clear and maintain gutter and drain
- Clean shelter and slab with high pressure
- Frame and screen are in good condition















SITE 4: CORNER OF NORTH ROAD & BEECHMONT ROAD, LOWER BEECHMONT, 4211.

















